

ITOP 6-3-038

PORTED-COAX SENSORS FOR INTERIOR APPLICATIONS

SCOPE

This document describes parametric considerations and functional test procedures for ported coaxial sensors (PCS) for interior applications. This procedure includes the measurement of the following: sensitivity, detection coverage, clutter, restoration time, and settling time.